

Tube forming processes a comprehensive guide

 I'm not robot  reCAPTCHA

Continue

on ManufacturingET.org March 1, 2012 TH6711 . M55 2003 Tags: Tube Bending Tube Formation Processes, Comprehensive Guide is a thorough guide with the latest developments in the field, the text discusses the best materials for bending and techniques and equipment for bending, cutting, branching, rationing and joining pipes. The book is suitable for beginners or advanced tube manufacturers. Information from leading industry experts covering the basics and guidelines for pipe manufacturing, pipe manufacturing and other areas. There is information about secondary operations required by typical manufacturers. The book also addresses management issues such as identifying appropriate tools and equipment, weighing costs and quality, and knowing the options available. 1 Pipeline Processes Comprehensive Leadership of the Society of Manufacturing Engineers GREG G. MILLER Association for the Formation - Technology Manufacturing / SME 2 Pipeline Processes: Comprehensive Guide i 3 4 Pipeline Processes: Comprehensive Leadership by Gregory Miller Society of Petroleum Engineer, Michigan Association for the Formation and Manufacturing Of Technology/SME 5 Copyright 2003 Society of Manufacturing Engineers All Rights Reserved, including. This book, or parts of it, cannot be reproduced by any means, including photocopying, recording or microfilming, or any information storage and search system, without the permission of copyright holders. The publisher has not claimed any responsibility for the use of the information contained in this. Although every precautionary measure has been taken in the preparation of this book, the publisher is not responsible for errors or omissions. The publication of any data in this book is not a recommendation or endorsement of any patent, ownership or product that may be involved. Library of Congress Catalog Maps Number: International Standard Book Number: X Additional Copies Can Be Obtained By Contact: Society of Manufacturing Engineers Customer Service One SME Drive, P.O. Box 930 Dearborn, Michigan SME Employees Who Participated in the Production of This Book: Cheryl zupan, Editor-in-Chief Walter Kelly, Editorial Consultant Rosemary Cszmadia, Production Manager Frances Kania, Production Assistant Katie Kwirk, Graphic Designer/Cover Design John Newberg, Production Editor Printed in the United States 6 For a tubaologist in all of us this book is dedicated to the hard work, perseverance, perseverance and perseverance of 7 Pipeline Processes: Comprehensive Guide to 8 Confessions of an Attempt to Be Accurate in All Areas of this book. Without their contribution, this book would not have been possible. There is no substitute for first-hand experience and knowledge, the next one Michael B. Cohn, Advanced Tubular Technologies, Inc., Waterford, Michigan; Ron Duvall, SMT Industries, Inc., Sidney, Ohio; Bill Holyoake, T-Drill Industries, Inc., Norcross, Ga.; Joe Ivasca, Tower Ail and Technology, Chicago, Illinois; Wally Jenson, Engelhard Joining Systems, Daytona Beach, Florida; Jeff Johnson, Finn Power USA, Inc., Schaumburg, Illinois; Dale Miller, Manchester United, North Manchester, IN; Todd Smith, J and S Machine, Inc., Ellsworth, WI; Ron Stange, Bend Tools, Denver, CO; and Bob Want, Tools for Bending, Denver, CO. Organizing the sheer volume of information in this text was a difficult task. Without the help of Carolyn Ghiglione, it would have been another 34 years before the book went to print. I thank her for bringing her highest efforts and many skills to this project. vii 9 Tube-forming Processes: Comprehensive Guide viii 10 Table Content Foreword ... 13th Process Planning... 1 Materials suitable for bending... 1 Copper and copper alloys... 9 Magnesium and Magnesium alloys titanium and titanium nickel alloys and high nickel alloys of cold-bending suitability Material shapes and trim Designing curves dimensional drawings Bent Parts Links Major Tube Cut-to-length Techniques Saw Cutting Lathe Cutting Rotary Rez Double Blade Cutting Cutting Laser Cutting Laser Cutting Laser Cutting : Comprehensive Guide to Stretch Formation Links Justification and Choice Equipment Bending Data Bending Techniques Of Reasoning Equipment Selection Purchasing Considerations Bibliography Tube End Forming Techniques and Design Tube Reduction Tube Extension Pipe Burning One-Paw Flank Double-Lap Tube Beaded Tube Groov joining the Tube Swaging Bibliography Tube Branching Techniques Commercially Available Tee Connections Fabricated Tee Connections Bibliography Brazing and Joining The Importance of the Management Process Basic Techniques of Joining Welding Design to Automate The Basics of Brazing Oxide Removal System x 12 Table Content Precleaning Parts Heating Cooling Summary Bibliography LUBRICATION Lubricant for The Making of Grease Application Finishing Operations Other Operations and Grease Lubricant Properties Summary of Pipe and Pipe Design and Inspection Of Pipes and Tube Design Inspection Techniques for Pipes and Tube Shape Bibliography Equipment Bibliography App: Theory of Plasticity Bending and Mechanical Behavior Metals Mechanics : Comprehensive Guide xii 14 Foreword The purpose of this book is to meet the needs of beginners as well as advanced pipe manufacturing operators. I've included a lot of data on pipe manufacturing and various other cross-sections, because I to solve much more than just making a tube. In any area, there is a lot of practical information that falls into the category of secondary operations required by a typical manufacturer. The book is located in 10 chapters, with information presented in a sequence that reflects the typical flow of manufacturing. The application consists of an appropriate physical theory that applies to many areas of metal formation, as well as diagrams and data that manufacturers will find valuable. The pipe manufacturing has advanced tremendously since packing the sand to keep the tube bending from the collapse. When I began to investigate the available written references to the manufacture of pipes, it became clear that the last real reference with any detail was The Cold Bend and Formation of the Tube and other sections written in most of this text, was adapted from this book, which is still very accurate in technical theory. Although the laws of physics have not changed, the technologies and processes that existed then have changed a lot. 133 16 Planning Process 1 The planning process planning process for systematically identifying the methods by which a product should be manufactured economically and competitively is an intermediate stage between design and production. It synthesizes factors such as: the functional requirements of the product; The amount of production required; Operations Necessary tools, materials and equipment and estimated production costs. Process planning contains specifications for the proposed production line on the process sheets, which in appropriate detail indicate the most effective sequence of operations, objects, and tools needed to produce the product. No method of planning processes is appropriate for all plants, and many methods are discussed in various other reference books that specifically address this aspect of production. However, in bending and shaping operations, certain steps are being taken in the planning of processes that deserve to be discussed in connection with the specialized nature of these steps. MATERIALS SUITABLE FOR BENDING machines are now widely used for: cold bending extrusions; hard rod and bar; moldings and rolled-up shapes; and tubes and pipes. 1 17 Pipe-forming Processes: Comprehensive Guide Typically, the most common metals can be cold bent, provided they have sufficient lengthening to reach the desired angle and radius before reaching their final strength. Metals usually formed easily include low-carbon and stainless steel, aluminum, brass and copper. Simple formation operations can also be performed on magnesium, titanium and some copper-nickel alloys. Special toolkit and bending techniques allow you to bend some of the so exotic and fire-resistant metals. Steel steel is the most common material formed on the bend of the machine, and those types of steel with a carbon content of 0.35% or less are the most practical for production work. With C The content is above 0.35%, the work solidifies going fast as the bend progresses. The loss of scrap due to the breakdown can be significant. As the carbon content increases, the bend radius should be increased and the angle of the piece should be as low as possible. The second determinant of suitability for a particular application is hardness. Steel with a Rockwell rating or less on a B scale is best prepared for production. Tougher materials usually do not have enough lengthening to bend before breaking. The American Institute of Iron and Steel (AISI) and the Society of Automotive Engineers (SAE) have developed specifications covering so-called standard steel as well as carbon and alloy steel. AISI designation system for standard carbon and alloy steels: 1. The first two digits of the four-digit series indicate the grade of steel. The last two figures indicate (as far as possible) the approximate middle of the carbon range. However, it is necessary to disassociate ourselves from this and to interpolate the figures in the case of certain carbon emission ranges, as well as for variations in manganese, phosphorus, sulfur, chromium and other alloy elements. Table 18 of the 10xxx 11xx 12xx 12xx Table 1-1 1-1 shows an abbreviated portion of the standard code of AISI carbon and alloy numbers. AISI Standard Carbon and Alloy Steel (Courtesy of the American Institute of Iron and Steel) Types and Classes Basic and Acid Open Hearth and Acid-Freemier Carbon Steel Steel Classes, Non-Ulfuric and Non-Phosphorized Basic Open Hearth and Acid-Free-Die Classes, resulfurized and rephosphorized Basic, open source carbon steel classes, rephosphorized and resulfurized 13xx manganese % 23xxx Nickel 3.50% 25xx Nickel 5.00% 31xx Nickel 1.25%, Chromium 0.60% 32xxx Nickel 1.75% , chrome 1.00% 33xxx nickel 3.50% , chrome 1.50% 40xx Molybdenum 41xx Chrome-molybdenum 43xx Nickel-chrome-molybdenum 45xx Nickel 1.1. 65%, molybdenum 0.25% 48xx Nickel 3.25%, molybdenum 0.25% 51xx Average chrome 52xx Chrome, High carbon 61xx Chrome-vanadium 86xxx Nickel 0.55%, chrome 0.50%, molybdenum 0.20% 87xx Nickel 0.55%, Chrome 0.55%, Chrome 0.55% 0.50%, molybdenum 0.25% 92xx manganese 0.80%, molybdenum 0.25% 92xx manganese 0.80%, silicon 0.80%, silicon 0.80% 2.00% 93xxx Nickel 3.25%, Chrome 1.20%, molybdenum 0.12% 94xx Marganese, nickel 0.45%, chrome 0.2 40%, molybdenum 0.12% 97xx Nickel 0.55% , Chrome 0.17%, molybdenum 0.20% 98xx Nickel 1.00% , chrome 0.80%, molybdenum 0.25% Letters attached to the full series of numbers of this steel to indicate the metallurgical process used are: The main open air of alloy steel; B acid-free carbon steel, C basic carbon steel with an open hearth; and E electric steel oven. 3 19 Pipeline Processes: A Comprehensive Guide to Simple Carbon Steel Based on Carbon Content, Simple Carbon Steel can be divided into three groups as follows: low-carbon steel with a carbon content of between 0.05% and about 0.25%, Medium-carbon steel with a carbon content of 0.30% to about 0.70%. 3. High-carbon steels containing 0.70% to about 1.30% carbon. Material in which carbon is not distributed evenly, such as corners or strengthening grades, re-rolled from the rail, should be bent to the most generous radii possible, and at the slightest angle. There will be a significant scrap because the high-carbon areas have insufficient lengthening to bend. Such material should be avoided, if at all possible. Alloy elements of the alloy are added to ordinary steel to change their behavior during heat treatment, which in turn leads to improvements in mechanical and physical properties. When choosing alloy steel for a specific application, the selected steel should contain no more than necessary for satisfactory satisfactory maintenance of operating conditions. Low-alloy steel. Low-alloy steel varieties can be divided into two separate groups: 1. High strength of structural steels, where fusion elements serve mainly to strengthen ferrite. Such steels are used as a rental state without heat treatment other than normalization or annealing. 2. AISI or SAE have become of higher quality than conventional structural varieties, where alloy elements primarily serve to improve mechanical properties over equivalent carbon steel, as well as to enhance steel response to thermal processing. Structural assessments. Highly strength structural steel is used mainly in the transport and construction industry for 4 20 process planning applications where steel with moderately high strength is not required and where weight loss may prove beneficial. The carbon content is usually less than 0.15%, although, in some of the higher-elastic varieties, steel can contain up to 0.30% carbon. While these higher carbon varieties have improved strength, they are less ductile and harder to form. Corrosion resistance, which is an important factor in reduced weight structures, is slightly superior to the resistance of equivalent carbon steels. This additional corrosive resistance is attributed to phosphorus and copper. AISI or SAE ratings. Low-alloy machine steels are usually characterized by high strength, good ductwork and excellent strength with proper heat treatment. AISI alloy steel is used, in particular, in the automotive and aviation industries for highly stressed members and moving engine parts. Some combinations of different fusion elements can, after appropriate heat treatment, give a certain steel unique and specialized characteristics for use in a particular application. For example, carbon-molybdenum and other steels have good creep characteristics and therefore find useful use for moderately high-temperature maintenance, where oxidation is not too serious. Typical applications are in pipelines steam and refineries. Nickel-chrome steel, as a group, demonstrate excellent hardening, high strength, good wear resistance, and durability. Various combinations of nickel-chromium, properly treated with heat, have tense properties, equivalent to the entire range, available with alloy steels. Chromium-vanadium steel, after heat treatment, show remarkable strength and good resistance to fatigue. Super-high-strength steel alloy. Several steels have been specially designed and applied at a strength of 200,000 psi (1,379 2,068 MPa). Examples are types 4140 and 4340. Modifications of these SAE varieties containing higher silicon have been commercially used, usually in a certain range of strength of 220,000 psi (1,517 1,724 MPa). Types 4130 and 4140 have become suitable for bending operations when higher strengths are desirable. Both are high carbon steel that should be used with the most generous radius possible. Since both work-harden quickly as the bend is done, the bend angles should be reduced by a small to keep the scrap to a minimum. Of the two classes, Type 5 21 Pipeline Processes: Comprehensive Guide 4140 will prove more difficult to operate and will require a larger radius than the same size piece of type that is due to its higher carbon content. Stainless steel. This family of steel is described by composition as containing 4% or more of chromium, usually more than 50% iron, and perhaps such alloys as nickel, molybdenum, Colombian, titanium, manganese, sulfur and selenium. These alloys give specific characteristics to increase resistance to corrosion and scalability, mechanical properties and formation at sub-zero, room and elevated temperatures. Stainless steel, in most common varieties, is usually bent without problems. There are three broad metallurgical classifications that have a noticeable effect on their usefulness of martensitic, ferritic and austenitic steel. The most common autoneic scores of the 300 series are formed; examples are types 304 and 321. Austenitic stainless steel is relatively easy to manufacture and weld. They are tough but ductile. They cannot be tempered by heat treatment; cold work alone can increase their strength. Ferritic steels are easily cold formed. However, low work hardening and relatively high yield strength combine to encourage localized thinning or neck down under strenuous stress. Therefore, caution should be exercised in cold formation operations, which include stretching. Since stainless steel usually has more elongation than soft steel, it can usually be formed for larger angles and on smaller radii than comparable carbon-steel material. Like all metals, For bending, hardness should be considered when showing the work of stainless. The best results are achieved when the blanks are between full soft condition and 1/4 difficult. When the surface of the surface appears Bending is paramount, a small amount of hardness must be present to eliminate the appearance of stretch marks (sometimes called orange-peeling state) on the outside of the bends. Evidence suggests that stabilized stainless steel has more homogeneous characteristics and is thus less likely to be broken. Since stainless steel is often used where the highest quality bends are required, a tool is often used that gives maximum control over the flow of metal through a close material conclusion. The material for such work, especially for the ultra-thin walls of the aircraft tube bend, must 6 22 Planning process must be carried out to close the measure tolerances. Pipes with walls of about an inch (1.24 mm) or heavier can be attracted to size. Lighter wall tubes should be purchased at-size, since size operations work-harden such material excessively and produce minute wrinkles, rather than changing dimensions through the metal stream. Stainless steel molds should be produced on a roll-forming machine if there is more than one break in the part. Roll formation produces more homogeneous forms. Heat-resistant super alloys. Many heat-resistant superalloys designed for use at temperatures of 1000 2000 F (538 1093 C) have high-color strength properties that surpass those of low-alloy steel and stainless steel. The three most important requirements of the alloy for high temperature maintenance are strength, surface stability and structural stability. Austenitic stainless steel was used as the basis for the development of high-temperature superalloys. The three main metal systems from which beneficial alloys have evolved are iron, nickel and cobalt. Because of the outstanding high-temperature strength of superalloys, they are inherently difficult to warp hot work, and many are sensitive to cracking during hot work. They also cause significant wear and tear on the die and roll materials. Alloys are also quite difficult to cool form. The Type 19-9 super alloy is used in the production of aircraft components. It will bend in the same way as the more common stainless varieties, but with its higher strength, it resists compression on the inside of the bend. Instead, it tends to form wrinkles. Careful attention should be considered by bending the machine with adequate power to form bends using the installation toolkit, which provides maximum stretch over the circumference of the bend. The tooling should be precisely set on the blank and exceptionally difficult so that it is not marked by the blanks should the wrinkles develop. Aluminum and Aluminum alloy is another widely formed metal. Unalloyed aluminum has many desirable characteristics, including its light weight, pleasant appearance, malleability, shapeability, and resistance to corrosive attack of industrial and marine atmospheres. 7 23 pipe-forming processes: Comprehensive guidance of many chemicals, and Products. It has good electrical, thermal and reflective characteristics, but has a relatively low level of strength and hardness. Three methods are used to enhance its strength and hardness: the addition of other elements for the formation of alloys; Thermal treatment of some types of alloys; and the strain of hardening cold work. The alloy designation Aluminum and its alloys are marked on a commercial basis in the United States by a series of numbers or numbers and letters assigned by the manufacturer to indicate the composition. Group 1xxx is classified as 99% minimum aluminum. The last two figures are the same as the two digits to the right of the decimal point in the minimum percentage of aluminum, when it is expressed to the nearest 0.01%. The second digit indicates a change in the limits of impurities: 0 indicates a lack of special control over individual impurities; and 1 9 (appointed sequentially) indicates special control over one or more individual impurities. 2xxx through 8xxx alloy group are assigned the main elements of the alloy: copper, manganese, silicon, magnesium, zinc and other elements, respectively. In these groups, the last two digits are randomly assigned to determine the different aluminum alloys in the group. The second digit indicates alloy modifications: 0 indicates the original alloy; and 1 9, assigned sequentially, indicates modifications of the alloy. The temperature designations for the temperament of aluminum alloys are based on the sequence of basic mechanical and thermal procedures used to produce temperament, but only those operations that are recognized as significantly influencing product performance are specified. If some other changes in the same sequence of core operations are applied to the same alloy and lead to different characteristics, additional numbers are added to the designation. The temperament designation follows the designation of the alloy and is separated from its dash. 8 24 Planning process Depending on temperament, all alloys are extruded as molds or tubes, or rolled and welded into a tube, suitable for bending. The nature of thermal alloys should be T6 or less; cold should be H-18 or softer. As with all metals, the more complex, less airborne alloys will require large bend radius for successful formation. Alloys usually bent include, H-12, H-14; 5052 in state 0; and T-6. The alloy 6063-T832 is usually bent, but on the radii at least once the diameter of the tube, and in the wall the thickness of an inch (0.89 mm) or more. While it may seem that alloys in a very mild condition are best adjusted because of their greater lengthening, bending tools are easier to note very soft metals. A relatively long clip length is necessary to distribute the clip force over a wide area and eliminate the distortion of the blank and the traces of the tool. COPPER AND COPPER ALLOYS WROUGHT copper and Alloys are available in a variety of different hardness or mores such as spring, hard, half-hard, and quarter-hard, designed with an appropriate amount of cold working after the last. In an annealed or soft state, manners are based on the specification of grain size, and grain size is the determining factor in the success of the formation. Strength tensions, yield strengths, and lengthening vary somewhat depending on the shape of the section. For flat products, the section is taken in .02 mm thick if possible. For the rod, the section is taken at 1.00-in. (25.4-mm) diameter, or if that is not available, to the closest diameter for which the data is available. The strength of profitability is a stress that corresponds to an increase of 0.50%. The data is in a mild state for an inch (0.05 mm) grain size or, if not available, the nearest grain size or annal is available. Commercially pure copper is available in several varieties, all of which have essentially the same mechanical properties. The three most commonly used (all the same purity, but different in some respects) are: electrolytic hard copper pitch, decontaminated copper, and oxygen-free copper. 9 25 Tube-forming Processes: Comprehensive Guide Copper Tubes are as extruded or extruded and drawn bent by many manufacturers. When considering copper for its formation, hardness is an important factor. Pieces in the range between fully annealed and semi-hard are commonly used for small bend radius, such as radii of about 1.5 times the diameter of the blank and larger. A tougher material will require bending radii two to three times the diameter or larger. The hardness of the skin is attached to a single light draw or zinc after the final anneal is considered most appropriate due to the risk of possible labeling of the tool in temperaments 1/4 difficult or less. When creating critical small bend radius in a thin-walled material, such as those used in U-shaped capacitor tubes, grain size is important. Copper-based alloys of binary alloys of copper and zinc are known as brass, and alloys of copper and tin - bronze. Some true brass, just because their color is similar to copper-in alloys, are called bronze. Similarly, the term bronze is also used in modern metallurgy to refer to copper, exhibiting a characteristic bronze color to which elements other than tin are the main fusion materials. Figure 1-1 plots percentage of lengthening and tense strength of different brass chemical compositions. Brass is widely used in bending, especially for the production of plumbing traps and elbows. The fully annealed material is best suited to bend the light-wall brass tube for central radii that are one to two times the diameter. Often the need for anneal just that the material is actually bent, leaving the length of the hard T to clamp against bend to die. Large bends of radius in all brass classes are usually made without annealing, and without any difficulty. MAGNESIUM AND MAGNESIUM The main characteristic of magnesium is lightness. While magnesium can be cold bent in some simple forms with large radii, formation has improved so much at high temperatures that most working magnesium is made hot. Small bends of the radius were made by heating the work to slightly elevated temperatures before forming. For example, tubes made of alloy A31B were bent at room temperature within a four-fold radius of 10 26 process planning drawings 1-1. The effect of the composition on certain mechanical properties of anal wrought brass. Diameter. The work of the same material in dies heated to 200 F (93 C) made possible bends three times the diameter of the radius. Heat ratings F (C) are widely used. TITANIUM AND TITANIUM ALLOYS The strength-weight ratio of titanium exceeds the ratio for most other engineering metals. As a result, titanium is increasingly used in the aerospace industry, where this ratio is a critical design factor. For convenient differentiation of various titanium and titanium alloy compositions, available commercial classes can be classified as commercially pure titanium, all alpha (single-family) welded alloys, alpha beta (two phase) welded alloys, and alpha beta in-verve alloys. The fifth group, alloys albeta, is available in the form of a leaf. 11 27 Pipe Formation Processes: Comprehensive Guide To Commercially Pure Titanium is an unalloyed composition containing more than 99% titanium. The remaining percentage consists of carbon, oxygen, nitrogen, hydrogen and iron. The amount of oxygen and nitrogen determines the strength levels. Various ratings are listed in the app of this book. All varieties are available in blanks, bars, wire, sheet, strip, tube, and some in extruding. In the group of commercial alloys there is one all-alpha weld alloy. It is 5% Al, 2.5% Sn alloy is available as a sheet, bar and wire. Alpha-beta weld alloys make up the majority of titanium alloys. They are warm-willed; They are all available in bars and blanks, and almost all in sheets. Titanium alloys containing 6% Al and 4% V have been designed for forging and are available in wrought-iron mill shapes. Alpha Beta, indigestible alloys are not cooked by thermoneural welding; Flash or slick welding can be practical for some. They are available in bar, wire, extrusions, sheets and forecres. Although only a limited amount of titanium has been formed on the bend machine, experience shows that certain varieties of titanium pipes can be bent. For best results, titanium for bending must be fully annealed, commercially pure alloy A-40. The process of annealing is very critical and can vary between pipe suppliers, individual blanks, and even between sections of the same tube. In diameter more than 3-0 (76.2 mm) the best results were obtained by bending titanium at elevated temperatures F (C). It's This. on the bend of the machine itself electric heating pressure to die and mandrel the body. The pressure accelerator dying is applied in many cases. By implementing careful material quality and temperature control, manufacturers have now formed thousands of bends. These include curves such as: 1.50 inches (38.1 mm) diameter; (1.25 mm) walls by 2-1 (50.8 mm) central line radius to 90; 1.25 inches (31.8 mm) in diameter; (0.89 mm) of the wall by a 1.50 inch (38.1 mm) radius of the central line to 110. NICKEL AND HIGH-NICKEL ALLOYS All nickel and high-purpse alloys have nickel as the main element, with the exception of Incoloy, iron-nickel-chrome alloy, and Ni-O-Nel, a nickel-iron-chrom alloy. High-purpse alloys 12 28 Process Planning are designed for specific service applications associated with high corrosion and/or resistance to oxidation in a wide range of temperatures. In addition, moderate anti-galing characteristics are developed in several cast alloys. Nickel alloys are divided into five main groups with the following typical characteristics and applications. Group 1 is a commercially pure nickel for chemical equipment, electrical use, high temperatures and corrosive resistance. It is also produced in cast form. Group 2, Monel, is a nickel-copper alloy for general use requiring corrosion resistance in addition to strength and high strength. The Monel is quite suitable for bending and is usually suitable in a way similar to common stainless steel varieties. Group 3, Inconel, is a nickel-chrome, heat-and-corrosion resistance alloy capable of withstanding temperatures of up to 2200 F (1,204 C). It has a high hot force, is resistant to progressive oxidation and fatigue, and is not magnetic. This alloy is also produced in cast form. Group 4, Incoloy 901, is an age-old nickel-iron-chrom alloy used for aircraft and industrial components requiring low creep and high rupture properties in the temperature range of 1000 1400 F (C). Group 5, Incoloy, is an iron-nickel-chrom, oxidation and heat-resistant alloy that also resists moderately sulphide atmospheres, green rot, molten cyanide salts, and fused neutral salts at high temperatures. The average room-temperature mechanical properties of forged high-nickel alloys commonly used for subzero, room, and elevated service temperature are given in the appendix of this book. The cold working characteristics of nickel compared to other metals are shown in figure 1-2. COLD-BENDING SUITABILITY When considering any material for its cold-bending suitability, the general rule is to use the next equation as a guide to determine the lengthening needed in the metal to make a given bend. 13 29 Tube Formation Processes: Comprehensive Guide Pattern Increase the hardness of various metals and alloys with cold work. 0.50D E and R Where: (1-1) E - required extension, % D - external diameter diameter material, b, (mm) R bend radius to the central line, V, (mm) Then compare the calculated elongation factor with the published elongation factor for this metal, either in the application of this book, or similar tables found in other references or reference books. It is quite common to make qualitative bends where the calculated lengthening exceeds the published figure. However, it is unreasonable to exceed the 14 30 process of planning published figures too far, such as trying to bend requires approximately 50% lengthening in metal having only 10%. MATERIAL SHAPES AND FINISHES In addition to material specifications, you should consider the shape of the blank. In the tube, the welding tube is often preferred to a seamless mechanical material, as closer tolerances remain between the outer diameter and the diameter of the pipes. This is especially important in lighter walls, where pulp should be used inside the tube to support the walls during the bend. Formed sections formed by hot rolling are preferable to cold materials, because hot working leaves have a higher percentage of elongation and thus allow bending to smaller radii and larger corners without excessive break. Bending machines are capable of producing a wide range of material forms. Tubing Tubing is the most often curved form of material. For the quality of bends and long life of the instrument, round welding tubes in steel or aluminum should be purchased as close to the specified diameter and as round as possible with modern processes of the pipe-rolling plant. Carrying out such quality control standards will result in consistent accuracy, no mar bends, and lower scrap rates. A welded flash should be considered if the inner pulp is used to support the tube during the bend. For critical bends, either flashremoved tubes must be used or mandrel should be grooved to accommodate the flash. Flash-in tubes are most commonly used and mandrel is done under size to accommodate the flash. You can expect a bend equal to the pulp gap. In addition, length tubes that have heavy burrs or dimple to the left of cutting surgery may require the ends to be deburred or de-dim, depending on the pulp gap and the number of burrs. 15 31 Pipe-forming processes: Comprehensive guide pipes should be free of abrasive dust, such as those left by an abrasive wheel. This is especially true for abrasives left inside the tube to be bent over the mandrel, because such dust will wear this tool excessively or cause pickup and breakdown. Excessive rust or dirt inside steel pipes can cause the same problem. Because of its physical properties, the aluminum tube can have a layer of oxide both inside and 24 hours. Pipes with only minimal oxide should be because oxide is extremely abrasive and will significantly shorten the life of the tool. Square or rectangular welded tubular alloy or rectangular rectangular Tubes, in steel or aluminum, should get almost the same attention as a round tube, but with an extra accent. Good material is held in uniform sizes. It is almost certain that mandrel be used in this work, and that it corresponds to the internal dimensions of the tube with only a few thousand days of inch (micrometer) clearance in general. Thus, the angular radii of the tube must be homogeneous. If any welded flash is present, mandrel should be grooved to take the flash. Since the musrel cannot be rotated from the plane, the tube must be purchased with a welded flash, consistently running along one point of the tube, preferably in the center of one side. Seamless tubes made from steel, aluminum, copper and brass, seamless tubes must be selected for bending based on the criteria of material uniformity and freedom from scale or surface oxide. In seamless steel pipes, the thickness of the wall often varies greatly, resulting in a varied interior diameter size. This condition makes it difficult to get the maximum efficiency from the use of the inner mandrel, if necessary. In addition, the concentricity of the internal and external diameters of seamless steel is usually not consistent, which can lead to sporadic appearance of wrinkles, excessive flattening or inconsistent accuracy of corner bending. Finally, the 16 32nd process of planning seamless steel pipes sometimes varies in hardness, leading to broken or incompatible springback bends. Seamless aluminum tubes are produced during the extrusion process and must be tested for the same differences in the thickness of the wall and/or inside and outside diameter concentricism as steel. Usually aluminum, as extruded, has a homogeneous hardness. The pattern after extrusion produces seamless aluminum. This eliminates inaccuracies and produces uniform tubes that do not present particular bending problems. Of course, such tubes should be free of tubular dimples and burrs, and have a minimal surface oxide. Copper and brass are most often bent like tubes that have been brought to their final shape by drawing. This presents several challenges to how to shape. The best life of the tool is if the tubes are used with a minimum of surface oxide. Often, brass tubes must be annealed, either in general or in a specific bending area, to make it suitable for bending. If this annealing is done in a gas stove or salt bath, the resulting film of oxide should be removed by nitpickling. This minimizes friction as the material is drawn over mandrel or through other stationary dies. The Lock-stitch Tubing Lock-stitch tube requires control than a seamless or welded tube, but is easily formed on a bend machine. Attention to two factors in the production or purchase of the specification lockseam greatly facilitates the bend. First, the seam should be rolled up as dense a lock as possible. To check the seam tightness, grab about 3-foot 3-foot length of material at both ends and twist the tube. If the seam lock is loose, it will produce a creaking or cracking noise or a shift felt. Such tubes align significantly more and produces a higher rate of scrap than the quality of the material rolled up to a tight lock. Second, changing the outer diameter of the tube increases the bending problem because the oversized or oversized material does not match the bend of the instruments close enough to allow the dying to control the flow of the metal into the quality of the bend. This factor is usually controlled at the point of cutting the steel stock before it is rolled into the pipes. 17 33 Pipe-forming Processes: A comprehensive guide to stainless clothing and butt-stitch or open seam tubes stainless-clad and butt or open seams two relatively unusual types of pipes formed on the bend machine. A stainless pipe is usually made by a roll forming a stainless steel sheet over an open seam, a soft steel tube. The stainless steel is held on the site of the castle seam rolled in the open area of the soft tube. This material is sometimes used where the production of large volumes compensates for the additional complexity of bending the stainless ocaping tubing. When used, the best results are obtained with a material having a layer of stainless inches (0.51 mm) in thickness or heavier, and where the two layers are rolled together as sturdy as possible. While this is not a direct consideration in the selection of material, it should be borne in mind that the bend of the stainless cladding tube usually requires the use of windshield wipers to die from aluminum-bronze, pulp, and unusually high pressure tools. These factors, combined, can lead to high cost of tools. In addition, the locked seam in the tube should be located directly inside or outside the bend, thereby limiting the use of this material. The material from the butt is formed from a strip of broth, rolled into a tubular form, but

drastically different. Common parts over a period of time are more important than the speed of movement of the machine's axis. It's This. It is simply impossible to bend the part at high speed because the previous bends will be deformed if the part moves too fast. This is especially true for small diameters and soft materials. In practice, few manufacturers operate axis machines at high speed when the accuracy of the part and repetitiveness are paramount. The number of interference moves, neo-axis movements, production controls, load/unloading ease, and part configuration are more relevant to actual cycle speeds than to axis speed. Capacity. The potential buyer should be interested in the capacity of the machine. Bender tanks should be estimated by the thickness of the wall, the outer diameter, the material and the radius of the central line. The yield points and other indicators of the strength of the material can be applied to the machine's mechanical level to determine the machine's capacity. A manufacturer producing large volumes of 1st (25.4 mm) parts should not buy a car with a rating of no more than 1 inch (25.4 mm). The consequences can have a direct impact on the life of the machine, the efficiency of the tool and the accuracy of the part. Buying a machine used today at maximum capacity can lead to problems tomorrow. Hydraulic system. Most semi-automatic and CNC-bending machines, especially large ones, use a hydraulic system. Effects of heat, cold, mud, etc., documented and im- port- 207-223 Pipe-forming processes: Comprehensive landmark guide. The most accurate machines should include a heat meter to maintain the temperature of the hydraulic fluid. It is common practice to provide fresh cold water. Additional water coolers and special hydraulic cooling systems are also available if water is not available. Hydraulic oil filtration systems are usually standard equipment. The quality of the filtration system, however, is not the same among machines. It is advisable to exhaust the options available. Servo drives. Servomotors that control the movement of the machine tend to alternate between current (AC) or direct current (DC). Early CNC machines used dc servos, and they have been the standard for years. AC drives provide better speed and accuracy, as well as less expensive, more compact and easy to replace. This is primarily due to the fact that they work cooler at high speeds and have a much higher acceleration and slowing ramp. They are common in most machines today. Service personnel can offer preferences based on their experience and judgment. Security devices. Semi-automatic machines usually come with a safety system to protect personnel from impact or pinched arm swings. Due to limited control capabilities and general requirements for bending machines, there are not many alternatives, except built safety systems or physical light security. CNC vehicles must be equipped with a safety mat to guard the front of the vehicle during operation. Double-palm buttons quickly replace the foot pedal Standard equipment. Other security measures can be easily added to the management format. Light fences, additional mats, fences, etc. can be added as long as they do not interfere with the tool area or parts bent. Serviceability. The service parts of the machine should be easy to find and identify. The valves and cylinders must have identification tags relating to function and electronics. Chain discs and wear plates should be easily adjustable and interchangeable. Grease fittings should be clearly marked and positioned to provide easy access. Grease fittings are usually called once a month. An additional automatic lubricant system can be reasonable for many companies. This will remove the error and facilitate much faster maintenance. Modern flexible machines do not require much maintenance, only consistency. 208 224 Justification and choice of power transfer equipment. An important mechanical aspect of the machines is the method of transferring power to the bend of the head for the degree of bend control. The curving head gets the greatest voltage of any movement that the machine makes. The buyer should pay special attention to rigidity, maintenance, flexibility and design. The most common and time-tested method of testing head bending is to use gear, sprocket, and chain communication to supply the strength of the arm swing. The systems have been designed to allow independent hand swings and motion tools, shaft energy transmission, belt drives, and rotary drives. Potential buyers should be aware that the size of the head bend can directly affect the machine's ability to produce parts. Specifications. The specifications are features that affect the specific functions of the machine. Manufacturers can vary greatly in this area, and differences can directly affect the performance of the machine. The potential buyer should pay discriminatory attention to the details of current and future needs. Multiple-radius capabilities. Many design engineers today indicate more than one bend radius. The feature offered by almost all CNC-bender manufacturers is the ability to bend the part on more than one radius of the central line. This is achieved by laying the toolhead. Then the part is passed between the bend dies. Another use for this feature is to transfer the part between the connection bending dies and other special tools. This can allow the parts to be bent in a single installation that otherwise may take two or more operations. The first method of transferring pipes between dying moves is the bend of the head. The head can move up, down and from side to side. This essentially moves the toolkit into a piece. The problem with that is that the heaviest part of the machine must be precisely moved and moved. The bend head is one of the areas of the machine that requires absolute rigidity to ensure the effectiveness of the tool and the accuracy of the part. Wear related to Additional moving parts can affect the overall accuracy and maintenance requirements of the machine. The second approach moves the bend of the head and parts. The instrument area can move from side to side, and the part, by positioning with the coach, moves up and down. Conversely, some machines move part from side to side and toolkit up and down. Special Tool 209 225 Tube Formation Processes: Comprehensive Guide and/or Parts of the Configuration may arise where this may be a necessary method. Any system still requires the turn of the most severe and critical area of the machine. The third method only moves a part. The tool area remains fixed while the carriage holding the part moves up, down, left and right. The rigidity of the tool area is not compromised, there are fewer moving parts to service, and there is greater flexibility in designing tools. Regardless of how the tube is transferred to bend multiple radii, you should pay attention to the placement of the tube, which is not straight. The onion in the tube can create problems. Most CNC benders use pipe support and/or a guide to provide a tube position in tooling. Although it is not necessarily standard equipment, it is crucial to ensure the success of bending multiple radii. Help with death from pressure. Pressure assistance should be considered an option for any machine with more than 3/4 inch (19.1 mm) power. The pressure to die help offers a significant improvement in the quality of the bend and a certain likelihood that efforts to eliminate mandrels and/or windshield wiper dies will be successful. There is no increase in cycle time, the cost is minimal compared to upgrading later, and the benefits are palpable. The clip for disembarcation. The drop-off clip is standard for most CNC machines. The machine's jamming zone is noticeably improved by the angular movement of the clamp-die assembly, which is partially drawn into the swing arm. This allows the formation of a more complex part with less chance of machine interference. Collecting. All machines have some collecting or tube-tooting tools. Most are a way to control how far a caller opens. This allows you to make a toolkit to understand beyond the installation or end of the form. It is important to note that some projects achieve this better than others. It is necessary to ensure that the internal diameter of the spindle is large enough to accept current and future projects. The most widely used collet in small machines includes three jaws. Four jaw systems are available for square or rectangular tube shapes. Large machines can use rubber collets or internal collets. Part configuration determines which method 210 226 Justification and choice of equipment extractor Mandrel and lubricant. Mandrel extractors and automatic mandrel-lube systems may not be standard on smaller machines. Big machines should definitely have an extractor mandrel. Automatic munrel lubricant can increase the life of the tool tool improve the quality of the bend by taking the margin for an error from the hands of the operator. Numerical Control Systems Computer technologies today offer unrivaled control over a variety of machine and programming functions. Discussion of computer functions in this book is mainly applicable to numerical control computers (CNC). The control system and software have a direct relationship to the performance of the machine. Computer technologies vary between manufacturers of CNC-benders. Therefore, it is important that the potential buyer has the practical experience with as many controllers as possible. Almost all working tube bend machines use components such as relays, power supplies, and switches common to many other electrically controlled devices. There should be a series of sensors and coders throughout the machine to provide machine position feedback to the computer. You can use 1,25 command boards to control the functions of the machine. It is important that the buyer focus on the functional aspects of the machine control system. Dust and heat-controlled electronics. Exposure to heat and dirt on complex electrical components can lead to machine outages and inaccuracies. However, modern electrical systems are reliable in harsh conditions. The computer systems used in cars are a good example of improvements made over the years for this type of application. Data entry. The data is usually entered through the keyboard and can be seen on the cathode beam tube (CRT) screen. Data input can also be done either by traditional buttons included on the CRT as a touchscreen or by a membrane panel. The traditional button approach can become sticky due to dust and dirt. Plastic treads are available to minimize the impact of dirt in keyboards. The touchscreen is very susceptible to grease and dirt on 211,227 pipe-forming processes: the operator's hands are a comprehensive guide. In addition, screens can be a source of frustration and slow-motion input, because it may be unclear which area has been affected and how many times. This is especially true when you enter sequences of numbers. The membrane panel offers the best approach. It is not subject to dust, can be erased easily and provides a certain position of contact. Color CRTs, graphics and large screens should be approached with caution. Simplicity and functional design should be the rule. Storage of data. You should avoid long-term storage in the electronic memory of the CNC controller because it does not provide a printed copy of the program. If the controller fails, the data may be lost. Constant storage is achieved by tape, floppy disk, data cartridge, or hard wire transferred to a secondary computer. Tape storage is probably the oldest method to date. Without Care, the tape may be damaged and the device will be susceptible to dirt. Use with secondary computers tape reader for data translation. Disk storage gives you an edge over other methods. Discs can be used on a secondary computer for additional manipulation of data. Floppies are less prone to crash due to dust and dirt. File management techniques are also simplified. Data cartridges are unique to this brand of equipment and are generally very reliable. Cartridges are expensive and require additional equipment for use on secondary computers. Linking a bender to a secondary computer is an option if the manufacturer wishes to store or manipulate data in another area of the plant. A secondary computer must have the necessary software to analyze the data transferred. Restrictions on distance from the bender and interference from high-voltage equipment should be considered. Data output. The printer in the control system allows you to get information about the part, what is in storage, and about the diagnostic functions of the machine. This is valuable information that can be used to validate data, manage storage, and improve diagnostic efficiency. Management of pedestals. Setting up the machine requires easy access to manual functions on the controller. Controllers are usually placed on a rolling pedestal or an adjustable column attached to the machine. Moving secondary pedestals 212 228 Reason and equipment selection provide start-up, stop and emergency-stop functions while the machine is operating. This reduces the time and effort required to load and unload the machine. Production management. Some controls are not common to all CNC machines. Intermediate pressure-to-die positions, plane-bend delays, and swing-hand-return delays significantly improve machine performance. Intermediate pressure-die positions allow the open pressure assembly position to die, which will be selected during automatic cycling. This reduces the movement of the machine, thereby improving the cycle time. Half of the die position can be irreplaceable when trying to cycle parts that are not straight. Basically, it acts as a guide to ensure that the tube stays in the bend-die tube groove. Plane-of-bending and swing-hand-return controls relays act as alternatives to programming avoidance or clogging movements. These latency controls provide a method for adjusting the machine's synchronization sequence. In many cases, this creates the need for a separate set of data in the program. This improves programming for data and machine cycle time. Serviceability. Unlike machine mechanics, the machine control system is something that service personnel are usually unfamiliar with. Line out of 10 machine problems not solved by maintenance personnel in devices caused by a malfunction of the control system. You should identify command and control tips that are easy to replace. Repeaters, switches and related components should be available. Sensors and coders must be resistant to dirt and avoid excessive wear and tear. Finally, an accurate maintenance guide and/or video recording should be mandatory. CNC software. The CNC-bender software should simultaneously increase the control system. Conventional software should not be taken for granted. The best way to be confident in friendly software is to get first-hand experience with the machines being considered. The following sections outline the main operational and control characteristics of the CNC-bender software. Operational software. The software that guides Bender's work is considered operational software. Although it is closely related to the control system, the operational software is a vehicle that tells the machine what it should do. In addition to controlling the machine's motion sequences through 213,229 tube formation processes: Comprehensive Closed Feedback Guide, this software provides critical data entry and channel format. Simultaneous programming. Being able to program the next part without interrupting production is a valuable feature. You can build multiple parts in advance, eliminating the need for computer recycling. Benefits directly reduce the transition time and increase the portion over a period of time. Consistent production. Consistent production is the ability to produce several different parts in a row. This can be useful for the production of multisteps assembly tubes. PRB extension. Typically, traditional position, rotation, and bending (PRB) data can be entered in the form of a diagram to create a bend program. The machine accepts information similar to that provided in Table 4-6. Table 4-6. Position, rotation and bending of data Part 11238 External diameter (25.40 mm) Material steel wall in. (1.65 mm) Bend radius in. (50.80 mm) Radius of the bend of an inch (63.50 mm) Although the categories of material, outer diameter and walls mean nothing for the machine to be stored with each part of the room. This ensures that materials are properly selected when extracting data from the store (see table 4-7). The loading position is where the wagon is when the operator gives a part. Offsets the position where the carriage moves for the table 4-7. Information stored from each part of the number 11238 Loading Position 104 Offset Position 88 Pressure-Die Point Collision 8 Bend-Die Point Collision 3 Booster Mode 5 214 230 Reason and Choice Equipment First Bend. Pressure and bend collision points are positions where the coach comes into contact with the instrument. Collision points protect the car and tools and are used as a reference for other movements of the machine. The booster identifies a stop-point for the aid unit to assist. Settings on this screen can be set numerically or by physically moving the wagon to the desired point and pressing the insert position. It is important that Note that all the bending machines are not the same here. The difficulty of entering these numbers ranges from simple keystrokes to scrap metal calculations (see table 4-8). This is where the specific bend data is hung. The dot number is automatic. The radius, the distance between the bends, the bend plane, the degree of bending and the speed of the axis for each can be entered sequentially or accidentally. Table 4-8. Bending data to enter the CNC system Distance between the radius of the process, bends the axis axis axis of the axis in. (mm) (Freed) Speed bending speed bending, Speed (25 4) (50.8) (50.8) Processes. Most CNC benders allow you to enter bends and cog movements on the bend. While this may seem excessive, many manufacturers have requested an additional increased capacity of more than 60 bends per piece. Manipulating and storing piece data in electronic memory allows the operator to access faster than relying on tape, floppy disks, cartridge, etc. It can also be used as temporary storage until the design part is completed. The process of debugging the new part of the program is much easier if the initial attempt can be broken down into separate movements of the machine. Interference points, tool modifications, and speed changes can be marked and corrected in this way. It is important to have 215,231 pipe-forming processes: Comprehensive guidance to note that each individual motion machine can be separated in a program to create individual bend sequences. The more difficult the part, the more likely it is. Management software calculates, measures, and records data to manipulate operational programming or to output to the operator. It can be valuable and is not always offered as standard equipment by CNC-benders. The following sections outline the main features available. XY' coordinates directly from CAD drawings or projects can be entered in the same way as PRB data. The coordinates are then processed and converted into traditional bend data. Cut length, extended length, and offset position are also calculated and displayed. This feature can be an excellent time saver if the engineering department is often behind. Reverse bend calculations. Many times the bend sequence makes it impossible to bend the part as entered. However, if it had been started from the other end, it would have been a cycle of fine. Reverse bend calculations automatically flip the tube over and start bending at the other end. This feature can shorten programming time and eliminate the great frustration associated with complex parts. Diagnostics. Three areas of diagnostic function should be standard equipment on machines with CNC bending with CRT output and printer. Some have a modem connection to connect to the manufacturer's service. First diagnosis determines the current state of normal functions such as activated emergency stop, automatic mode, illegal data and manual mode. This first diagnostic area is regularly used by the operator and is the first logical step in finding the machine problem. The second diagnostic area is the machine's performance indicator, which should provide a systematic overview of every large mechanical system on the machine. All cylinders and side engines must be positioned and identified if they do not reach the target location. This identifies a cylinder or engine malfunction and the possibility that position sensors are not working properly. 216 232 The rationale and choice of equipment The Third Area, I/O monitoring, should provide data on entry ports, exit ports and codeframes. Binary code readings on these systems indicate which command printed board or encoder is faulty. It is normal practice to fax this display to the central service center. Trained professionals can analyze this information much faster than most maintenance personnel. If the object is within the ride, the service technician sends spare parts at the postal service night. This approach is fast and economical. Springback and lengthening. Springback is measured manually depending on the degree of bending, then it is automatically applied on a straight basis to determine the value of compensation. Thus, a 90 bend measuring 2 springback applies to the bend program for 45 bends like 1. The extension is measured automatically or manually and applied to the bend program. This is achieved through closed feedback between the carriage and the head bend. For example, if the machine makes a bend, the rear end of the tube should move forward at a given distance, given the bend radius. The machine measures this difference and applies it to the bend compensation values for the distance between the bends. Counter and work reports. The counter provides the operator with a method of accurately determining the desired and produced required number of parts. This can eliminate the incorrect calculation of the production run. Work reports can display and print daily task times and count a series of production launches. Reports measure the actual time of cycling, the number of parts produced and the time during which the machine is in automatic operation. They provide the evaluation or industrial engineering departments with specific data on cycling. They can also be used to justify automatic system loading based on actual annual loading and unloading times during a production run. PURCHASING CONSIDERATIONS There are intangible factors that are separated from the immediate physical properties of the machine They are 217 233 Pipeline Processes: Comprehensive Leadership should be conducted in high regard, but should not dictate the selection process Possibly). Delivery is always a problem. Bender manufacturers often stock up on more popular models of machines. If the machine is ordered in a warehouse, it can usually be delivered anywhere in the United States within one or two weeks. Ordering a specific machine at the plant can take four to six months. The characteristics of the manufacturer characteristics of the bend-machine company is considered to be important. The manufacturer of the Benders tube should have a good reputation and be solvent. The best way to learn about the manufacturer is to talk to people. A potential buyer needs to figure out who is using the machine manufacturer and see what kind of business they doing using people in the pipe-making business should be called. A small study before committing significant capital expenditures can prevent a disaster. Location Choice Machine based on where it made discounts the whole selection process. Capital equipment should stand on its merits. Personal preferences should be rejected in favor of doing what is right for the company. Protectionism does not affect American competitiveness abroad and is inconsistent with capitalist ideals. Conversely, it is wrong to buy based on the idea that, because if it is from a given place, it should be the best. The equipment supplier organization has a significant impact on the overall success of the project before and after the purchase. Service calls of technicians cost \$per hour, plus costs. The availability and qualification of service personnel directly affect 218 234 The rationale and choice of equipment for the cost of calling the service. Recording the ability to modify electrically programmable programmable memory-only (E-PROM) programs and provide RS232 or other interface methods may indicate the competence of the service organization. This may not be necessary for the buyer now, but future changes, maintenance, expansion and automation bender requires this experience. If possible, it may be appropriate to visit the manufacturer's service facilities to determine the extent of spare parts stock and the quality of service technicians. BIBLIOGRAPHY Miller, Gregory G Reason Pipe Bender Shopping. Dearborn, MI: Society of Manufacturing Engineers who justify, choose and implement pipe-bending techniques. Dearborn, MI: Society of Manufacturing Engineers. Stange, Ronald R Major tube bending the manual. Dearborn, MI: Society of Manufacturing Engineers. 219 235 236 Tube End Formation 5 Tube End Formation METHODS AND DESIGNS Pipe end forms are essential for many tube applications. They are used to create some type of connection with other media (tube, hose or block). In most cases, they can be formed by any style of the tube, although there are some discussed further in this chapter. The formation of a cold end is a process that has been around for many years, but many changes have been made by the automotive industry. Finding cleaner, lighter and better ways to move fluids through systems found in the car fuels research for stronger end forms. Tolerance has been tightened to minimize the possibility of leaks. The elimination of the rations has also spurred some of the best projects. All this history and innovation positions the shape of the end of the tube as an essential part of the fluid processing systems found in many products. There are five main forms that can be applied to the end of the tube: reduction, extension, flash, ball, and impact (thickening). Cuts and extensions are simple if both are not made on the same end of the tube. Consistent cuts and extensions can create many problems. Burning allows you to use the end view in many new applications. Beading has advanced significantly and allows engineers to keep the best tolerances and produce the best compounds. These apps are discussed in detail throughout this chapter. 221 237 Tube-forming Processes: Comprehensive TUBE REDUCTION Guide Depending on the product being formed, ram formation is one of the most commonly used methods of reducing the tube. This method holds the tube motionless and forces you to reduce the impact above the end to reduce the diameter of a particular section. The 5-1 figure illustrates the shock of completing the tube. For some applications, the pilot can be added to create a reverse extrusion that will control the internal diameter. The main impact on the reduction (see figure 5-1) consists of four sections of passage for the tube. The tube is part of the so-called tube-sized section, which is no more than the outer diameter of the starting tube. Capturing this section helps maintain the tube and minimizes the backup or bulge of the material. Then the tube is in the transition section, which begins to reduce the tube to the desired measurement. The tube is then moved to an area of size that controls the outer diameter of the end of the tube. The final punch area provides relief for the tube and the usually oversized inch (0.13 mm). This area minimizes friction on the pipe as the impact passes through the cycle. It also helps prevent springback on the end of the tube. Springback gives a flared look to the end of the tube. The thickness of the wall, the strength of the column and the composition of the material play an important role in the degree of reduction. All these drawings are 5-1. Jaws and reduced impact. 222,238 Tube End Formation above the elements, the average reduction for each operation is 2 times the thickness of the wall. Each type of metal reacts differently. The general rule for total carbon and stainless steel is the softer material (annealed), the better the tube reacts to a cut kick or die. The tube can be reduced to 20% in diameter. Conversely, the more complicated the more likely that the tube under the decline emphasizes as he tries to try retreat from initiating force. Copper and aluminum tubular materials tend to react in reverse order. The strength of the column is smaller in the softer material, and the tube tends to go away and start from the force. Reducing the thickness of the wall by 2 times can exceed the possibility of a softer material, and the degree of reduction should be reduced. When cuts are much higher than 2 times the thickness of the wall is required, then a few cuts are needed. Reducing the tube by more than 20% can cause the tube to plunge into the transition zone. Instrumentation of wear and tear are important factors to consider when reducing, because the initiating force in the kick takes the greatest punishment, and that, in turn, can change the size of the outer diameter. When the size of the end of the tube has been changed, the wall will thicken and the length of the tube will increase. The following equation can be used for practical but not precise value for growth in length: D'L'D, where: d d I (5-1) L - tube length, B. (mm) D - external tube diameter, b. (mm) d - internal diameter tube, B. (mm) D 1 - outer diameter section reduction or expansion, b. (mm) The purpose of the completed tube dictates whether the outer or internal diameter is relevant. Some aluminum tubes allow you to control both the external and internal diameter. In most common applications, the outer diameter is usually a controlled party. The size of forming a punch in the right dimension and forcing it over the tube end can reach control. Admissions range from 223,239 pipe-forming processes: A comprehensive guide based on the use of the finished product and tubular material. Most often tubes the size of a V. (0.13 mm) tolerance. In general, when creating a contraction, the inner mandrel is not needed. A material that has low strength may need mandrel if the tube has a tendency to collapse in the transitional impact section. When a part requires control of the internal diameter, it is likely that the outer diameter has control or tolerance placed on it. The next operation involves a blow with the size of a mandrel for the inner diameter. This kick looks like all other blows except the tube flow will only be for relief. This ensures that the stack-UPS is properly tooled and minimizes the transition. Although problems are created, most configurations can be formed. In the figures 5-2 and 5-3 the tube is carried, which controls the outer diameter during the reduction of the tube. The internal pilot will pass through the tube while the impact is being retracted. Diameter and the size of the outer diameter of Figure 5-2. 5-2. extrusion (position to jaw). 224 240 Tube End Formation Figure 5-3. Reverse extrusion (jaw entry position). Tools must line up and perform the size at the same time to ensure unified consistency throughout the reduction. The premature-size effect can be an intolerant end form. The transition section is the key to the quality of the end forms and the longevity of the life of the tool. The angle during the transition should give the best results. More than 30 angles can cause tube wrinkles, or if the strength of the tension is low, the tube can bulge and push back into the face of the jaw. Following this corner is a radius that mixes the tube with an area of size. The radius should be approximately 0.25 inches (6.4 mm) long. This radius will help reduce friction and prolong the wear of the punch. When a steeper angle is required than 30, the percentage reduction should be lower due to the higher compression load forced onto the tube. Where the angle of the cone is smaller than recommended, the percentage reduction is less due to the friction build-up from the larger impact surface exposed by the tube. For these reasons, the 30-on angle of the cone supports the least friction-compatible pressure. Reducing the area is a key factor in the success of the reduction. The correct lubricant and pressure valve to drop into the punch also provide proper formation. 225 241 Tube Formation Processes: Comprehensive Guide to TUBE EXPANSION Expansion, of course, the opposite of reduction. Unfortunately, there are a few variables in the tube that make the previous statement not so easy, at least in any situation. Several situations may require fewer or more bumps. The first element to consider is the method by which the end is formed. There are three common methods. Method A uses a ram machine. This method uses the same method and is usually the same machine as the abbreviation. Differences are first seen in the formation of the punch and the clamp of the jaws shown in the 5-4 pattern. The enlargement punch resembles the inner diameter of the tube. There's a 5-4 pattern. Expanding punch, tube and jaws (expanding jaws). 226 242 Tube End Formation may be some difference, depending on the degree of cone angle present during the transition punch. The impact can also be an insert attached to the end of the tool. This is to ensure that the extra travel time required to strike is necessary. Spray the transition time tooling, and minimize the cycle time and tool cost. The ram or axis of the traverse forces the tool into the tube, creating an extension. If the inner diameter of the tube is crucial, the end can be formed outside the jaw. When the outer diameter should be controlled, it is best to form an extension inside the jaw cavity. The purpose of containing the ram is to minimize or arches that can be formed in most aluminum, carbon and stainless steel. By using the impact into the tube creates a great load on the outer walls, and they tend to bow outwardly. The jaw clamp cavity squeezes the material back into the punch. The angle of the transition also plays a role. No more than 15 corners of the transition period are difficult to reach. The radius at the beginning and end of the transition helps speed up the process of making a hit, and prolongs the wear period by extending the expanding impact. The sharper the angle, the greater the tube trend to try to continue flowing towards the corner. All the same factors that apply to reduction are applicable in this form: the thickness of the wall, the strength of the column, and the composition of the material. Expanding more than 135% tube diameter can thin the wall and possibly crack the material. A second or third impact of expansion should be added to the operation when the extension gets closer to 135%. When other extension tools are added to the operation, the degree of formation should be evenly distributed between the impacts. If two strikes are used, the first strike should expand 50% of the desired size, and the second blow should expand the remaining 50%. The tool's lifespan is extended and better extensions should be made. The same restrictions on the strength of the tube column used in the reduction also apply to expansion. A tube with low column strength folds up when the strength of the ram exceeds the strength of the tube wall. The actual strength of the column changes along with the tubular material and can affect tolerances. Tube with tolerances for 227,243 pipe-forming processes: Comprehensive guide inside and outside diameters is difficult to hold if the thickness of the wall is uniform. Copper tubes have the most difficulty holding both tolerances. Traditionally, the thickness of copper pipe walls can vary +0.013 inches (+0.3 mm), while the industry standard for other pipes is +0.003 inches (+0.08 mm). As with most types of end forms using the ram forming method, lubricant is very important. It is recommended to draw a combination of good lubrication and high strength of the film. There is not a single oil that fits all situations. Different metals require different formulas. The operator must contact the lubricant supplier to get an accurate formula for the pipe requirements. The power of the punch/tool is also very important. Heat kick treatment helps to increase hardness and prolong the duration of wear. In some cases, a thermal diffusion process is necessary when dealing with high wear strokes or abrasive tubes. This process should be taken into account at the end of the formation of most steel pipes. The volume of the ends that need to be formed and the type of final form should also be factored into the decision. Two other methods of expansion formation, B and C, are radial-force rolling and radial-axial force Accordingly. Accordingly, B is effective when you need to achieve a relatively sharp transitional shoulder. The clamp jaws work the same way they did in previous examples. After the jaws clamp the tube, the mandrel extension enters the tube and then compresses the tube against the cavity in the jaw clamp. Most or all of the tube's ovality can be removed and close tolerance can be carried on the outer diameter of the extended section. This method is especially suitable for roll-sized pipe ends. Radial-force rental minimizes the effect of variations in the thickness of walls. The welding flash on the welded steel pipe can be reduced due to the compacting effect of the expansion of the mandrel. Extending length can be a problem if it is more than 2 inches (50.8 mm). The material tends to deviate and the tapered extended section usually results. Figure 5-5 shows the C extension method, which can smooth out the section as it expands. This form end method can be used to penetrate further into the tube than the radial extension method since interaction with the length of the tube can be limited to a relatively short distance. The deviation of the expanding mandrel within the limits of Mandrel fatigue does not have the same detrimental effect on the maintenance of the size faced by 228 244 Tube End Forming Figure 5-5. Expanding the tube with axial and radial forces. The method of B. Tube lubricant is not essential for methods B and C due to the rolling action of the mandrel. When the diameter increase is severe, cladding and a small chamfering operation are recommended. This prevents fractures from beginning at roughness points at the end of the tube. The length of the tube is reduced by all three methods, because the transverse area in the extended section is larger than the transverse area of the starting tube, and the length is collected to make a difference. The 5-1 equation can also be used to give an approximate length of reserves needed to obtain the desired extension length. Compensation can be resolved in the transition zone from the size of the tube to the extended section. Cross area at 229,245 Tube Formation Processes: Comprehensive pipe cutting halfway through the transition can be used for practical purposes. It is not uncommon to experience an unequal length reduction about the circumference of the tube. The larger the expansion, the more pronounced this characteristic is. This result is more pronounced on a welded steel pipe than on seamless pipes. TUBE FLARING Single FlareRing is defined as extending or opening the outside end of the tube. In this process, the same three methods of extension formation are used, because in fact there is an extension. Method A, illustrated in figure 5-6, uses the process of formation of a ram. The same ram-forming machine used to reduce and expand can also burning. This end-forming style is the most versatile all-purpose has a faster cycle time than other methods. These benefits are also transferred to a machine that is cheaper to operate. The clamping of the jaws is the same except the burning occurs in the flash cavity cut to the jaw. The impact resembles an expanding impact only with the entry and transition area. In most cases, this kick is an insert that fits into the impact holder or tool holder. This reduces the cost of the toolkit and facilitates the transition of the toolkit. A punch or tool passes the nose hitting the tube, which helps the center of the tube. The transition area extends the tube to the jaw cavity, creating a flash. Most single outbreaks are made in a single operation. Method C (Figure 5-7) is a compromise between methods A and B, as radial and ovalform forces in the game to get one flash. The radial and lash forces are each smaller than those required by methods A and B. Methods B and C are the intended flash site through a mobile impact action or instrument without the use of a higher formation pressure. Shorter clamp blocks can be used by C than A method required. Method C works best on larger-diameter pipes with a thicker wall. Method B, shown in figure 5-8, uses only radial forces for formation, which requires more bias to form a single flash than method C. This requirement limits the use of method B in size 230 246 Tube End Forming figure 5-6. Flash blow with tube and jaws. pipes with a diameter above 0.75 inches (19.1 mm). The tubes should be loaded over the mandrel/tool and against the shoulder on the mandrel/tool for correct positioning. The B clamp pressure method, sufficient just to compensate for radial pressure formation, allows for shorter clamp blocks than methods A or C. This function is desirable when the clamp area is very minimal and when a serious increase in the diameter of the flash is required. Rolling allows you to gradually form around the circumference of the tube. The thickness of the metal in the flash cones from the thickness of the tube wall to the minimum wall at the outer diameter of the flash. The inner angle of the flash is always larger than the outer corner. This thinning is less pronounced with rolling techniques than with straight line or ram forming method. Incorrect tuning of rolling tools without adequate pressure and control of passage can over-bomb the metal seat. 231 247 Tube Formation Processes: Comprehensive Guide Figure 5-7. Rolling flash with a led and radial force. Flare Double flashes are found in applications that connect one tube to another, thereby minimizing the leakage path. For example, a laminated tube or welding tube provides a stronger base of connection for tubular assemblies. Two methods of producing a double flash internal double flash and external double flash. Inside the Double Flare The first method, inside a double flash, is the most common double flash. It's This. Two flash kick operations, but requires only one 232 248 Tube End Formation Figure 5-8. Rolling flash with radial force. set of jaw clamp eliminating the need for a transition tool. Figure 5-9 shows the first operation, which is a single tube flash and produces disorders for the next operation. The second incineration strike puts the tube back on itself and closes the ball. Coin pressure is desirable to provide a satisfactory place. There is little or no thinning of the metal wall as the precipitation process places the metal predominantly under compression stresses. The end of the tube becomes a flash seat with a double circle. (The presence of a circular ring in the seat is sometimes misinterpreted as the beginning of a fracture.) The width of the flash site is limited to the size of the diameter of the balloon. Attempts to exceed this limit can lead to the collapse of the metal formed in the double ball at the first operation. Welded carbon steels have the potential to break along the welding seam. With this application, you need to use a higher grade of steel. 233 249 Tube Formation Processes: Comprehensive Guide Figure 5-9. Double flash (first and second surgery). Outside of Double Flare, the B method shown in Figure 5-10 is commonly referred to as the external double flash. Once the tube clamps the jaw in place, curling the blow curls of the material and back into the jaw face, creating a ball at the end of the tube. The second operation requires changing the clamp of the jaws to those that have a burning cavity in the front. The second blow of the operation then close the ball, creating a double wall. Little or no thinning walls are experienced. Coin pressure is again desirable to ensure seat quality, and analysis of curling operations shows limitations in the size range and width of the seat. The external curling radius should be 2 to 2-1/3 times the thickness of the tube wall. The increased diameter of the end of the cork places the metal under stress, which is limited by wiring (percentage lengthening) of the metal. Strike Action sets friction from behind the surface of the 234 250 Tube End Formation Figure Method B to produce a double flash. 235 251 Tube Formation Processes: Comprehensive Guidance Works. Excessive friction when the tube's surface comes into contact with the impact can cause stress that exceeds the strength of the column of the unsupported part of the tube. As a result, the tube buckles or collapses before impact. This friction, when carried out within reasonable limits, creates compressed tensions to balance stress. Thus, little has changed in the thickness of the wall. SINGLE-LAP FLANGE Single-atein flash is used in several applications, including locking nuts and connecting to a mold or metal plate. Two methods are usually used to form the same flank. The first method (figure 5-11) uses the formation of a ram to influence the tube. The jaw clamp ensure the tube is in place, the nose of the first impact enters the tube, and the conical transient area directs the material to erupt. The jaws remain closed, and the second blow goes forward and moves the end of the tube back against the jaws chasing the surface. The advanced position of burning the punch should be controlled to avoid excessive pressure, to build up in the radius between the flash and the tube. Failure to limit forward traverse-burning kick can lead to unnecessarily thinning of metal and test failure. Only the percentage lengthening (extension) of the metal limits the height of the flank. For example, if the physical properties of the metal indicate an elongation of 30% to 2 inches (50.8 mm), the diameter of the flank may be about 30% larger than the diameter of the tube. For a standard welded steel tube, the diameter of the flank should be limited to a 25% increase for good results. Under certain circumstances, a single-can-see operation can be performed with a single blow. The first combustion operation can be eliminated if the flank height is low in proportion to the diameter of the tube, and the outer radius of the transition between the outside of the tube and the back of the flank is equal to or exceeds the thickness of the wall. The second method of forming one flank rolls the end with radial pressure force. Figure 5-12 demonstrates the process. This rolling method is only suitable for swinging pipes above an inch (19.1 mm) diameter. The method allows for formulations of relatively high flanks in a single operation. Spiral serrations at 236 252 Tube End Formation Figure Method A for one circle flanging tube ends (direct line of motion). outside the flank seat is caused by the formation of a radius of transition between the horizontal and vertical work surfaces of the flank mandrel. The larger the transition radius, the less pronounced is the appearance of serration. As in the first method, the percentage of material lengthening limits the height of the flank. 237 253 Tube-forming processes: Comprehensive method of A-list guide B for one circle flanging tube ends (rolling with radial force). In both methods, if the desired flank is relatively high, consider cladding and chamfering operations before flanging. The quality checks before and after the formation must be performed, because any rough edges or dents present on the pipe can be the starting point of fractures as the metal thins during formation. DOUBLE-LAP FLANGE Double flank is a closed ball, transferred to the end of the tube, providing a double thickness of metal in the flank seat. When the diameter of the flank does not exceed 125% of the diameter of the tube, the method of formation of the ram can be used in one operation. When the diameter of the flank exceeds 125% of the diameter of the tube, the large open ball at the end of the tube should be rolled up force on the first operation and then closed the ram formation in the second operation. 238 254 Tube End Formation Tube BEADING Tube Beading has probably seen the most growth and progress among many different end forms. Internal roll formation methods have good tolerances, but are usually slower. Ram formation has developed and become a faster solution, with most beading applications in the automotive field using this method. When high production volumes are mandatory, the short cycle time yields good results. Method A uses axing pressure and provides a wide range of beading possibilities. The machine and jaw clamp are the same style as used in previously discussed endformation techniques. In most cases, clamping jaws have serrations cut into the jaw cavity. The serrations, which range from an inch (mm), are perpendicular to the pressure of the aus, which prevents the tube from sliding back into the jaw. Serrations should be a part of each jaw where the pressure is applied (see figure 5-13). Figure Jaws serration pattern. 239 255 Pipe-forming Processes: Comprehensive Guide Simple Ball with a height% of tube diameter can be formed in a single hit application. The thickness of the wall should remain the same, giving the ball a thickness twice the thickness of the wall. When forming very large beads over 200%, it is best to end up with some pipes and then cut them through the middle and measure the thickness of the wall. The ball can form either in the jaws of the clamp, or in the shape of the impact. Both applications are quite equal in function and quality, but if there is a difficulty, the formation of the ball in the cavity of the jaw clamp gives a better chance of recovery of the operation. For example, if there is too much exposure outside the jaw material, excess material fills the jaw bead cavity and flows out of the jaws. When the jaws open, the tube can usually be removed. When a tube ball is formed inside the punch, the excess material first fills the punch cavity and then flows out. In some situations, when the punch returns home, the end of the tube is separated from the clamped tube and sticks to the punches. This end of the form is extremely difficult to remove from the impact. The formation of the ball in the jaw clamp is the method most recommended by toolbox providers. A completed product usually dictates the method by which the o-ball is captured. Ram formations can also be used to form a ball larger than 140% of the diameter of the tube. This end shape uses clip jaws to hold the tube, which is extended to desired ball heights by using an extension punch. There may be some minor walls thinning that depends on the amount of expansion. Once the extension is complete, another impact passes and reduces the tube to the pilot's diameter. The third blow moves forward forms a ball. It is best to form a ball in a kick with this scenario because it avoids making the jaw clamp jump on or blow. The three-stroke end-forming machine also eliminates costly tool transitions because the tool owner indexes each tool into a position of formation. Several beads can be formed using extension and reduction techniques. Some double or hose ball/foot beads end shapes can be completed in one stroke with a single stroke with sliding jaws. Sliding jaws consist of two sections. The first one holds the phone in place. The front section also clamps on the tube, but moves backwards and an inner ball appears as soon as the kick hits the front of the jaw. The punch forms the front ball as soon as the rear ball is formed. 240 256 Tube End Formation of the distance between the two beads is the determining factor of how effective this method is. The composition of the material and the thickness of the wall determines whether the sliding jaw process can be used or whether the secondary attachment of the jaw would be better. The diameter control of the ball is affected by many different variables. The material flow should always be evaluated because it varies depending on the tube material. Controlling the flow with the pilots in the impact significantly improves the sequence. The thickness of the wall is also difficult to control. Soft copper, for example, makes the diameters of the ball vary. Outside the jaw the material directly affects the height of the ball. Capturing the ball in the jaw or in the impact can control the height of the ball. Adjusting the tube stop in the right position captures this material. All of the above elements, as well as the machine, which has good repetitiveness, helps to ensure a successful process of beads. TUBE GROOVING There are two main grout operations. The roll groove exerts radial pressure on the tube with control or several rollers to force the material to the desired diameter. The incision groove again uses radial pressure with one or more incisors to remove the material and avoid the outer ball. This book discusses the use of multiple rollers and incisors in comparison with single rollers and incisors. Restrictions on material flow and control are also considered. Roll grooving uses radial force on a stationary tube. The incision groove uses a thinning wall. Compressed material counteracts the internal load caused by drawing the material into the groove. The pressure clamping technique is similar to the formation of a ram. The clamp jaws also serrations to hold the tube and prevent movement. Again, serrations should be around about an inch (mm) deep and run longitudinally with the tube. The tubes receive energy from force initially from its end and tries to draw the force in the direction of the clamp should be proportional to the number of rollers and the depth or cutting. Actual rolling can be done with one or more rollers. One roller method needs minimal clamp pressure because the roll involved on 241 257 Tube Formation Formation A comprehensive guide tube is very small. However, this method requires more radial force. One roller requires a mandrel that rotates with a roller to ensure the uniformity of the ball and help in carrying tube sizes. A multi-roller system has some advantages. The radial force may be smaller due to several commitments on the tube. Three rolling tools allow you to better control the tube, produce a better part and hold tighter tolerances. The tube positioning stop is located on the mandrel to ensure the correct position of the ball (figure 5-14). Mandrell is stationary, acts as a support for rollers, and provides a proper diameter of the tube end. The material tries to fold at the end of the tube because the strength of the tube is weak at this point. The speed of rollers, which varies depending on the thickness of the wall and the composition of the tube, can increase the pressure. The time of the machine cycle varies from tubular material to rolling operation: operation with multiple rollers is faster than operation one. Systems with three rollers have more tools on the tube at the same time than two-lime systems, and are recommended for working with close tolerance. The material will usually flow from the point of contact, and back to the clamp of the jaw. Thinning walls is minimal, but can occur on both groove radii. The depth and sharpness of the groove are directly related to the amount of thinning. Drawing a grooving tube (radial force rendered by several rollers). 242 258 Tube End Formation shallow groove with small angles can not thin. The groove depth of 20% of the diameter of the tube can cause some thinning and need groove radii. The walls (another ram-shaped operation) before the groove is cut. Multiple grooves present other problems because many deep grooves create too much contact with the surface and can twist or tear off the end of the tube. Cut grooving actually removes the material from the tube end, and there are limited circumstances where it can be used. This operation is best performed on O-test aluminum. Tolerances and groove depth are factors to consider when evaluating a cutting operation. The end of the tube must first go through the wallthinning procedure. This consists of using a ram-forming machine to impact the end of the tube, which causes the material to flow back from the impact. When exposed, aluminum tends to thicken; Steel tries harder to maintain its column strength and push through the jaws. The punch controls the outer diameter of the tube and causes thickening to occur in the outer diameter. The inner diameter of the mandrel supports the inner wall to keep the tube from crushing on itself. Once the operation is complete, the tube can be transferred to the winding machine. In most cases, one groove can be shortened for surgery because the end of the tube cannot maintain much contact with the surface. Too much and the end of the tube turns or tears out of the tube. Tube. The cut groove can be held in tight tolerance and radii. The top four tubes in 5-15 cut grooves with sharp radii. The bottom three tubes rolled the groove. These tubes show a more gradual narrowing at the bottom of the groove. TUBE ATTACHMENTS Brazing was the main method of adding attachment to the tube. In recent years, the trend has shifted to the end of the formation to block the attachment in place, eliminating many costly ration operations. However, depending on the application, some attachments may need rations to provide a non-leak surface. First of all, it depends on the material flowing through the tubular assembly. One of the most common operations, used mainly in automotive air conditioning systems, is the locking of an aluminum-connective unit on an aluminum tube (Figure 5-15b). 243 259 Pipe-forming Processes: Comprehensive Guide Pattern (a) Cut grooves with sharp radii and (b) roll grooves into aluminum tube ends. (Courtesy of Manchester Instrument and Die) A direct line or ram formation is used in making these finite forms and fixing blocks. The first punch reduces the tube to an amount that depends on the outer diameter of the tube and the diameter of the attachment hole. Usually the tube shrinks enough to move the block on it. If the tube eventually gets to cut the groove, then the impact can be performed with the same cut kick. Next hit: 1. raises the attachment during the first operation; 2. rotates the attachment into place; 3. Crosses forward to attach the block, and at the same time, extends the tube to block the block on the pipe. The third impact reduces the size of the pilot's tube and leaves a transitional area for the fourth impact to form a protective ball. Over 244 260 Tube End Pressure Formation is necessary because the tube affects several times and the greater clamp force pushes it a bit out of the round. The last two operations depend on the application of the tube assembly. Another common attachment is the ferrul, which is used when the tube is attached to the hose to complete the assembly. The surface of the ferrula, which comes into contact with the tube, is very narrow and requires a double ball lock. The ball is formed with the first punch and tube the size of the inner diameter of the hole of the ferrul. This punch also leaves some transient material that is used for the second stroke. Usually this type of tube/hose assembly requires a rolled or prickly groove at the end to disrupt any leakage pathways. The next operation requires the transfer of the tube to the grout operation. The tube is clamped and the grout tools perform the operation. The tube can be placed in the frame of the end of the former. Once the tube is clamped, the punch lifts the ferrul and pushes it onto the tube. At the same time, the punch captures material and creates inner beads, which which ferrul in position. Some pipe-forming machines are built with a frame-end-forming system and several roll-grout systems that allow the pipe to remain clamped while the end formation and grout head slide into position. This process ensures better repetitive machine and process. Once the ferryl is secured, the tube is ready for the next operation, which consists of loading the hose into the ferr and pressing the two together. SWAGING Rotary Swaggers Rotary is a mechanical forging process used to reduce the diameter of symmetrically transverse rods or pipes to a circular

flow with approximately 1,981 F (1,083 C), depending on traces of metals included in the alloy. Since the flow temperature of these alloys exceeds the active level of any ration flow, the extinguishing requires a hydrogen atmosphere or vacuum furnaces. Different types of furnaces will be discussed later, but they all reduce oxides by catalytic action of the hydrogen atmosphere furnace or by extinguishing them in an oxygen-free vacuum. Copper alloys are mainly used to extinguish carbon and alloy steel, stainless steel, nickel and copper nickel. Since the alloy of filler is high-flowing at flow temperature, interference fits of the joints are recommended. If the fit-up is free fitting, sometimes iron or nickel sawdust is added to the copper paste to enhance the properties of the fillet. Aluminum alloys. AWS identifies two aluminum filler alloys for aluminium rations. However, the Al-718 is the most popular to use in the entire industry. It consists of 88% aluminum and 12% silicon; its solid temperature is 1070 F (577 C) and the liquid temperature is 1080 F (582 C). Al-718 is widely available in all forms: wire, rod, preform and paste. It is used for rations 3003, 6061 and 6063 aluminum main metals. Al-719 can offer favorable advantages because the average temperature difference between the melt temperature of the widely used metals of the aluminum base and the flow temperature of AL-718 can be as little as 25 F (4 C). The recipe for this filler alloy contains 76% aluminum, 10% silicon, 10% zinc and 4% copper. The temperature is 960 F (516 C) and the liquid temperature is 1040 F (560 C). Unfortunately, due to the small demand for the An-719, today it is only available in the form of pasta. Manufacturers who use aluminium in the production of their products are constantly studying new and exotic aluminum alloys to make basic components. Some are looking for lighter pipe formation processes 289 305: A Comprehensive Guide to Aluminum Alloys for the Machine; other users are interested in the heat-learning characteristics of various aluminum alloys. While there may be very good reasons to use these new aluminum metals in production, some cannot be successfully brazed until new filler alloys and streams are developed. FLUXES As metals heat up, oxides are formed on surfaces exposed to heat. The only purpose of the thread is to raise that are formed on the faying surfaces of base metals connected as they heat up to prepare the surface for the alloy filler. This process is commonly referred to as called wetting the surface. The parts components must be thoroughly cleaned before rationing to remove grease, oil and other dirt to get optimal strength and maximum penetration of the alloy filler into the joint interface. Brazing flow can dissolve pollution, but residues of pollution, along with residues of flow, can remain in the faying surfaces of the joint after rations. The connection of base metals does not occur in the space occupied by interface pollution. Once the ration is cleaned, the contamination can be removed leaving empty voids. If these voids extend from the top to the bottom of the joint interface, a leakage path can form. If the void is internal to the joint, fusion diffusion may not occur. As a result, these areas of the joint are not strong; In some applications, the joint may fail due to stress. Fluxes are made from a variety of ingredients tailored to reduce the oxidation of specific metals as they heat up. Typically, an active flow lifestyle depends on temperature and time. As the stream heats up outside the recommended temperature range, or outside the active life of any of its ingredients, it becomes inactive and unable to continue to protect the metal surfaces during ration surgery. Specific ingredients included in different types of flow are selected based on the fact that the base metals are overextended, the temperature of the filler alloy flow and the estimated amount of time it takes to complete the ration. The 290,306 Brazing and Joining Formulas used in the production of streams are usually property. However, most commercially available streams include ingredients from the following list: Used in high-temperature flow, borotas fuse at 1400 F (760 C), and stay effective above that temperature. They have a good oxide-dissolving action but viscous and require mixing with other materials to increase the flow. Boron powder improves fluxing action at high-vex ranges to protect fireproof materials and oxides of chromium, nickel and cobalt. Fluoborates reduce the high temperature oxides of the flow compound. Fluorides reduce the high temperature oxides of chromium and aluminum and improve the flow of borats. Chlorides work in the temperature range lower than fluorides, and depress the melting point of fluoride. Boric acid facilitates the removal of glass residues of flow after rations. Lithium salts dissolve aluminum oxides in aluminum streams at ration temperature. Alkalia, or potassium hydroxide and sodium hydroxide, increase the useful flow temperature. They dissolve and become liquid, absorbing moisture from the air. They have a short shelf life. Wetting agents to facilitate the flow of the flow before brazing. Water is present in connection with the ingredients of the flow or in the additions to the thread for consistency. Fluxes forms are made in the form of paste, powder, suspension, liquid or Pasta is the most common form and is now available in a creamy form for convenience. Typically, specific streams are available for rations of aluminum, aluminium-bronze, silver, magnesium, as well as for high-temperature applications. Dosed versions are becoming popular because of the benefits they offer in managing the process. 291 307 Tube-forming Processes: Comprehensive Guide to Dispensers flows distributed streams are applied using a manual or automatic gun applicator. The benefits of dosed streams include health and safety factors because brazer is less likely to come into contact with the flow, and environmental considerations because less is washed down the drain after rations. As the recurring deposit is distributed to each joint, it becomes easier to predict the annual usage requirements. However, the most important advantage of the dosable flow is its ability to improve and control the ration process by distributing repetitive flow deposits in successive locations at each joint. This is important because the amount of flow applied to this joint increases the total mass in the joint area, which must be heated to brazing temperature. Inconsistent flow deposits change the amount of heat (BTUs) that must be caused to the joint area to increase its temperature to the point of the filler alloy flow. Flux also has a reflective characteristic that changes the rate of heat absorption, reflecting heat from the joint being brazed. The consistent placement of the deposit flow allows a consistent heat directed in the joint area being brazed. Controlling the total mass of all ingredients in the heat zone improves the quality of rations. Other characteristics including homogeneity gap around each joint being brazed, thermal output, and time should be consistent to get high results for first time bandwidth in automatic brazing applications. The generic fluxes White Stream is the most common and is used for low temperature rations of most metals, except aluminum, magnesium and titanium, which are brazed with silver-based filler alloys. This type of flow is usually active to about 1600 F (871 C). The flow becomes transparent before the temperature of the ration, making it easy to see the flow of the alloy filler. It is easy to wash off after rations. Boron and other ingredients are added to white streams to increase their active range to about 1,800 F (982 C) for massive components that require long-term heating, or high-dark-th coincided- 292,308 Brazing and Joining perature alloy filler. This type of flow works well when used at lower apt temperatures, and is recommended for stainless steel, carbide or rations long-term heating. These threads are commonly referred to as black streams. Aluminum streams Are usually two popular streams available for rations of aluminum. They're Them as corrosive or non-corrosion-based activity residues after ration. Sodium chlorides and fluoride are used for corrosive flows; non-corrosion flows are formulated using potassium chloride and fluoride. The main advantage of corrosive aluminum streams is that they are active over a long temperature range, thus providing the oxide-free surfaces needed for proper fuze of the filler alloy. The process window is usually more forgiving because the flow is active for a longer period of time than is typical of non-corrosion threads. Assuming that all other variables that normally affect the quality of braze are controlled, it may be easier to get high results for first time bandwidth when using corrosive streams. Parts brazed with corrosive streams appear clean and shiny after cleaning in 20% solution of nitric acid and water with at least two freshwater rinses. The main reason for choosing a non-corrosion flow is that after rations are not required after ration. However, you should consider a number of other characteristics related to the use of this product before deciding on the type of thread to be used for a particular application. While the activity level of non-corrosive streams is very active at low temperatures, the actual life expectancy is relatively short. As a result, the process window is reduced because the link surface faying must achieve a brazing temperature while the stream is still active. The narrow window is caused by a short active flow time, which increases the difficulty of synchronizing the ration cycle time. As a result, it may be more difficult to reach high first-time bandwidth levels, which can usually be achieved by using corrosive aluminum streams. During the ration, free flowing, the non-corrosive stream dissolves in the surfaces of aluminum base metal. The flow extends to 293,309 pipe-forming processes: A comprehensive guide across the entire outer and inner surface in the thermal area around the joint, leaving behind a rough, abrasive, white surface. This cosmetic condition may be undesirable for some types of applications. Duration and unsightly appearance are the two main reasons why many decide to use corrosive streams and invest in after cleaning the processes needed to remove the residues of corrosive flow. OXIDE REMOVAL SYSTEMS In addition to using braze flux to reduce surface oxides during non-oven operations, steam or gas currents can be used to reduce external oxides, and inert gases to reduce oxides from the inner surfaces of the part. Gas gas is usually formulated from a mixture of boron and acetone. Sometimes it is called the flow of steam. Typically, fuel gas is prescribed through a liquid mixture placed in a closed tank system (see figure 7-7). As the mixture and fuel gas come out of the torch, acetone acetone spreading the national mixture over visible and invisible parts of the flame. Flames are usually clearly defined, changes in green color and becomes thick in appearance as normally invisible parts of the flame absorb the boron mixture. Boron, as it comes into contact with moisture in the air, turns into boric acid, a widely used ingredient in the production of rations. Boric acid, completely distributed throughout the flame, establishes a protective barrier enveloping the thermal surfaces of the part. Boric acid in this application is non-corrosive and does not require post-cleaning. The safety barrier is the main function of the gas flow. No post-cleaning is required when it is used for rations of copper or brass as long as the filler alloy containing phosphorus is used and no braze flow is applied to the joint. The stream only protects the external surfaces it comes into contact with during heating. Since the flow of gas is usually unable to reach deep into the faying surfaces of the joint, it may not be able to protect these surfaces, allowing oxides to form during the heating process. Gas Flow 294 310 Brazing and Joining Figure 7-7. Gas flow system. should not be replaced by rations as a way of eliminating after cleaning after rations. Nitrogen cleansing While many companies use nitrogen, most inert gases can also be used to displace the space occupied by atmospheric air on the inside of the assembly. Cleaning the inside with nitrogen reduces the likelihood of oxidation on heated internal surfaces during rations. Inert gases are slowed down by the formation of oxides, but they do not remove those that have formed. Thus, the flow should be used, except when copper-phosphorus alloys are used in rations of copper metals. PRECLEANING PARTS Unfortunately, pre-cleaning parts is one of the steps that is either completely altered or completely eliminated due to its cost and environmental problems, which it sometimes creates. Flux has not developed 295 311 pipe-forming processes: A comprehensive guide to pre-clean parts components. The decision to remove the pre-cleaning operation can lead to poor ration quality and increase the cost and scope of the operation after cleaning. Any oil and pollution left in the heat-affected area is likely to be carbonated and become very difficult and costly to remove. Pre-cleaning processes range from wiping the components of the part with a cloth to partially immersing them in low-fat liquids. The problem with wiping is that oils and other contaminants cannot be completely removed. Residual contaminants remain in pores located on metal surfaces. In addition, pollution from one placed on subsequent parts rubbed with the same fabric. Dive the tube into the skimming liquid oil leaves on the upper surfaces. Capillary attraction draws oil down and into While heated. In addition, skimming is generally unable to remove other types of pollution, such as dirt and heavy oxidation. Explosion of beads is an acceptable method for removing pollution; however, the media should not contain silicon. Basic streams are not able to penetrate and dissolve silicon, which is extremely difficult to remove from the pores of base metals. Its presence prevents the fusion of filler. HEATING Heat source selected for a specific application should ensure uniform heating within the joint area of the part that is brazed. Capillary attraction does not occur if the base metals are not heated to the temperature of the filler alloy flow. However, if the heat is directed at the filling alloy, it can melt into the faying surfaces of the joint. This condition is commonly referred to as cold alloy flow. However, optimal strength is not achieved and the phenomenon of alloy diffusion does not occur. This condition is one of the main reasons for the recycling and scrap in the manual ration process, because the hand brazer has difficulty producing a repetitive and uniform thermal pattern. The trend is to devote a process to each application on the machine to get repetitive. Whether the induction or torching process is used as soon as a single thermal pattern is determined, it can be difficult to recreate it during the transition process. However, sup- 296 312 Brazing and Joining pliers of both of these types of equipment are developing methods to eliminate the transition. The purpose of the heating process is to increase the temperature of all parts components evenly. Massive components require more heat. Thin, light parts require less heat. The efficiency of the heating process is determined by how well the heat system chosen for a particular application works. The Gas Systems Gas System provides a simple and inexpensive location of torches in specific models to evenly cause heat in all assembly components, especially in applications that use multiple thermal stations on the machine (see figure 7-8). Gas systems direct heat to specific assembly components, while limiting heat induced to others. This is important in rations, which include components from different base metals and masses. Gas heating systems are also automated because of the ease of designing a thermal pattern. Systems are available that offer a digital transition to ration different components on a single machine. Gas systems have some limitations that can make other heating methods a better alternative. Since large heavy parts require more heat (BTUs) than smaller ones, it may take too long to heat the joint area before the flow temperature of the filler alloy. When (a) (b) (c) Figure 7-8. System Heating. 297 313 Pipe formation Comprehensive guidance of this condition exists, a high risk for the elimination of alloy filler also exists. The longer the time it takes to increase joint temperature, the greater the potential for conducting heat away from the joint and in delicate areas at the assembly. This can be especially important if sensitive materials including rubber, springs, diaphragms and painted surfaces are located next to the joint being brazed. In addition, the finished size of the assemblies with the formed tubes near the joint can be distorted due to the heat, easing the stresses created during the formation. Induction systems Induction system provides an effective method of inducing heat to a certain area of the part (see figure 7-9). Localized heating is a major advantage of the induction system as it reduces the time it takes to heat the joints to brazing temperatures. This is especially important when putting out heavy massive parts. Carrying out heat away from the joint is limited. Because the induction figure is 7-9. Induction heating system. 298 298 tube forming processes a comprehensive guide pdf

[fb76908ca8.pdf](#)
[8219952.pdf](#)
[2c029f.pdf](#)
[3796915.pdf](#)
[ejercicios de velocidad y aceleracion](#)
[combat obscura torrent](#)
[libros de quimica pdf secundaria](#)
[walk through walls: a memoir](#)
[rotel rap 1580](#)
[euskal gramatika osoa zubiri pdf](#)
[biochemistry jeremy berg pdf](#)
[ahs cluster headache guidelines](#)
[pink floyd breathe tab pdf](#)
[perimeter composite shapes worksheet](#)
[acute lymphoblastic leukemia treatment guidelines](#)
[coolorus 2. 5. 9 crack](#)
[hacked spotify apk for iphone](#)
[minot builders supply billings mt](#)
[meiosis vocabulary worksheet pdf answers](#)
[normal_5f8c08227ce51.pdf](#)
[normal_5f8fc804dadc8.pdf](#)
[normal_5f87834496f45.pdf](#)