

EASA PART 145 APPROVED AERONAUTICAL PRODUCT CAPABILITY LIST

Aircraft Structural Contractors Pty Ltd.



Unit 22, Axis Industrial Park, Pasturage Road Caboolture
QLD 4510 AUSTRALIA

Telephone Number: 07 5499 1181 Facsimile Number: 07 5499 1184

Email Address: Graeme@ascpm.com.au

AMO approval certificate reference number: EASA.145.0766

Aeronautical Product Capability List AMO Form W-23

26/08/2019.

EASA PART 145 APPROVED AERONAUTICAL PRODUCT CAPABILITY LIST

Form No:

W-23

Form Rev Date: 25/03/2019

AIRCRAFT STRUCTURAL CONTRACTORS AERONAUTICAL PRODUCT CAPABILITY LIST

RATING	ATA	P/N	Designation	Manufacturer	Reference of the CMM	Level of Maintenance	Workshop
C7 Engine - APU	78	99A9253M	T/R Blanket	Darchem Eng	737 SL-78-050-B	Repair	Sheet metal
C7 Engine - APU	78	99A9254M	T/R Blanket	Darchem Eng	737 SL-78-050-B	Repair	Sheet metal
C7 Engine - APU	78	99A9265M	T/R Blanket	Darchem Eng	737 SL-78-050-B	Repair	Sheet metal
C7 Engine - APU	78	99A9266M	T/R Blanket	Darchem Eng	737 SL-78-050-B	Repair	Sheet metal
C7 Engine - APU	78	99A9267M	T/R Blanket	Darchem Eng	737 SL-78-050-B	Repair	Sheet metal
C7 Engine - APU	78	99A9268M	T/R Blanket	Darchem Eng	737 SL-78-050-B	Repair	Sheet metal
C7 Engine - APU	78	315A2295-236	Thrust Reverser Assy	Boeing	CMM 78-31-40	Repair	Sheet metal/Composite
C7 Engine - APU	78	315A2295-243	Thrust Reverser Assy	Boeing	CMM 78-31-40	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A2700-22	TE AFT Flap I/B RH	MHI	CMM 57-53-09	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A2700-28	TE AFT Flap I/B RH	MHI	CMM 57-50-09	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-7	TE AFT Flap O/B LH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite

EASA PART 145 APPROVED AERONAUTICAL PRODUCT CAPABILITY LIST

C8 Flight Controls	57.50	113A3700-12	TE AFT Flap O/B RH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-19	TE AFT Flap O/B LH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-20	TE AFT Flap O/B RH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-21	TE AFT Flap O/B LH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-22	TE AFT Flap O/B RH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-23	TE AFT Flap O/B LH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-24	TE AFT Flap O/B RH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-25	TE AFT Flap O/B LH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-26	TE AFT Flap O/B RH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-27	TE AFT Flap O/B LH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A3700-28	TE AFT Flap O/B RH	Boeing	CMM 57-53-08	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A4100-3	Spoiler Assy Ground #1	Boeing	CMM 57-56-63	Repair	Sheet metal/Composite
C8 Flight Controls	57.50	113A4100-4	Spoiler Assy Ground #12	Boeing	CMM 57-56-63	Repair	Sheet metal/Composite
C8 Flight Controls	27	113A9252-1	Tail Cone Assy	Boeing	MM 27-51-28	Repair	Sheet metal/Composite
C8 Flight Controls	27	113A9350-1	Fairing Assy	Boeing	MM 27-51-18	Repair	Sheet metal/Composite
C8 Flight Controls	27	113A9350-203	Fairing Assy	Boeing	MM 27-51-18	Repair	Sheet metal/Composite
C8 Flight Controls	27	113A9352-1	Flap Fairing Tail Cone Assy	Boeing	MM 27-51-18	Repair	Sheet metal/Composite
C8 Flight Controls	57.40	114A5010-11	L/E Slat #1	Boeing	CMM 57-43-01	Repair	Sheet metal/Composite
C8 Flight Controls	57.40	114A5010-207	L/E Slat #1	Boeing	CMM 57-43-01	Repair	Sheet metal/Composite

EASA PART 145 APPROVED AERONAUTICAL PRODUCT CAPABILITY LIST

C8 Flight Controls	57.40	114A5020-4	L/E Slat #7	Boeing	CMM 57-43-02	Repair	Sheet metal/Composite
C8 Flight Controls	57.40	114A5020-212	L/E Slat #7	Boeing	CMM 57-43-02	Repair	Sheet metal/Composite
C8 Flight Controls	57.40	114A5040-208	L/E Slat #5	Boeing	CMM 57-43-04	Repair	Sheet metal/Composite
C20 Structural	53	284A1801-4	Radome Assy	Boeing	SRM 53-10-72	Repair	Sheet metal/Composite